

GOVERNMENT OF WEST BENGAL  
Irrigation & Waterways Department  
Jalasampad Bhawan, 3rd Floor, Western Block, Salt Lake,

Memo No:GO2223013501IW

Date: 08/02/2023

File No:IW-14011(19)/1/2023-SECTION(IW)-Dept. of IW

From:- JOINT SECRETARY(WORKS)  
Irrigation & Waterways  
GOVERNMENT OF WEST BENGAL  
Irrigation & Waterways

To:The  
Chief Engineer (Mech. & Elec.) , Irrigation & Waterways Directorate  
Executive Engineer, Teesta Mechanical Division , Irrigation &  
Waterways Directorate

Subject:Administrative Approval for the Essential repair, maintenance and servicing work for rabi boro irrigation of h/r, c/r and distributary gates at different locations of TMLC, MMC, KTI and DNMC and replacement of damaged cable of TMLC Tail Ragulator gate under TBP in the Block of Rajganj, Jalpaiguri sadar, Phansedewa, Chopra and Islampur, within the District - Jalpaiguri, Darjeeling and Uttar Dinajpur during the year 2022-23 (SCHEME ID--IW/IR/T-002-2223),Project ID:- IW222372347S000

The undersigned is directed , by order of the Governor, to say that the Governor has been pleased to accord Administrative Approval for the Project Essential repair, maintenance and servicing work for rabi boro irrigation of h/r, c/r and distributary gates at different locations of TMLC, MMC, KTI and DNMC and replacement of damaged cable of TMLC Tail Ragulator gate under TBP in the Block of Rajganj, Jalpaiguri sadar, Phansedewa, Chopra and Islampur, within the District - Jalpaiguri, Darjeeling and Uttar Dinajpur during the year 2022-23 (SCHEME ID--IW/IR/T-002-2223) ,the details of which has been given below.

Name of the Project: Essential repair, maintenance and servicing work for rabi boro irrigation of h/r, c/r and distributary gates at different locations of TMLC, MMC, KTI and DNMC and replacement of damaged cable of TMLC Tail Ragulator gate under TBP in the Block of Rajganj, Jalpaiguri sadar, Phansedewa, Chopra and Islampur, within the District - Jalpaiguri, Darjeeling and Uttar Dinajpur during the year 2022-23 (SCHEME ID--IW/IR/T-002-2223)

Project ID: IW222372347S000

Address : Block-Rajganj, Jalpaiguri sadar, Phansedewa, Chopra and Islampur, District - Jalpaiguri, Darjeeling and Uttar Dinajpur.

Administrative Approval: Rs 5363000 (Fifty Three Lakh Sixty Three Thousand Only.)

Phasing amount and chargeable head of accounts

Sl No.	Financial Year	Head	Scheme Type	Scheme Name	Amount
1	2022-23	32-2700-80-001-00-001-19-00-V	State Development Schemes	Maintenance Expenditure in Irrigation Sector	5363000
Total					5363000

This order is issued with the concurrence of FINANCIAL ADVISOR ( Irrigation & Waterways) of this Department vide their / his U.O No. AA2223033638FA00 Dated 07/02/2023.

  
JOINT SECRETARY(WORKS)

Government of West Bengal  
Irrigation & Waterways Department

Date: 08/02/2023

Memo No: GO2223013501IW

Copy forwarded for information and necessary action:

The Principal Secretary / Secretary-(Irrigation & Waterways Department)

The Principal Accountant General(A&E)-West Bengal

The Principal Accountant General(Audit)-West Bengal

The Principal Accountant General(RW/LBA)-West Bengal

The Financial Advisor-(Irrigation & Waterways Department)

The Finance Department-(Group-F&N)

  
JOINT SECRETARY(WORKS)

Government of West Bengal  
Irrigation & Waterways Department



**SCHEME ID : IW/IR/T-002-2223**

Name of the Main Scheme :- Essential repair, maintenance and servicing work for rabi boro irrigation of h/r, c/r & distributary gates at different locations of TMLC, MMC, KTI and DNMC and replacement of damaged cable of TMLC Tail Ragulator gate under TBP in the Block of Rajganj, Jalpaiguri sadar, Phansedewa, Chopra and Islampur, within the District of - Jalpaiguri, Darjeeling and Utter Dinajpur during the year 2022-23

Consists of following Sub-estimates:-

Sl No.	Name of Sub-estimates as per tender	Tendered amount (Rs.)	Contingency 3% of amount put to tender (Rs.)
1	Rabi/boro repairing and maintenance work of Gate Shutter and hoisting arrangement of H/R of Dy-2/TMLC, c/r at 0.09km, c/r at 3.18km, c/r at 6.72km, c/r at 13.47km, c/r at 29km of Dy-2 of TMLC, H/R of M-3 at 6.7km of Dy-2/TMLC and H/R of Corola flushing of TMLC all within the block of Rajganj, Jalpaiguri Sadar and Haldibai of Dist- Jalpaiguri	1892003.00	56198.00
2	Rabi/boro repairing and maintenance work of Gate Shutter and hoisting arrangement including painting of C/R gate at ch 2.882 km of Dy 7R of MMC at Block- Chopra, PS-Chopra, Dist-Uttardinajpur, West Bengal	1294992.00	38465.00
3	Installation of new Gate Shutter and hoisting arrangement for Rabi/boro irrigation including painting of C/R gate at ch 2.155 km of Dy 5A of MMC at Block-Phansedewa, PS-Phansedewa, Dist-Darjeeling, West Bengal	165256.00	4909.00
4	Rabi/Boro maintenance work by Oiling, greasing and replacing of damaged bearings, nutbolts etc and painting of 259 nos regulator gates at different locations of TMLC, MMC, KTI and DNMC under TBP at Block- Rajganj, Jlpaguri sadar, Phansedewa, Chopra and Islampur, Dist- Jalpaiguri, Darjeeling and Utter Dinajpur, West Bengal	942002.00	27980.00
5	"Replacement of XLPE Al armoured cable 4C X 95 sq.mm for restoration of power of TMLC Tail Ragulator Gate at Fulbari, Block-Rajganj & Phansidewa, P.S-N.J.P & Phansidewa, Dist- Jalpaiguri & Darjeeling, West Bengal"	914000.00	27149.00
<b>Total:</b>		<b>5208253.00</b>	<b>154701.00</b>

**Estimated Cost of Main Estimate.- Rs. 5362954.00**

  
Joint Secretary Works  
Irrigation & Waterways Department