

:-0353-2542586 :-0353-2545174 e-mail:setbc2012@gmail.com

Government of West Bengal Irrigation & Waterways Directorate Office of the Superintending Engineer Teesta Barrage Circle Teesta Sech Bhawan, 2nd Mile, Sevoke Road ,Siliguri

Dt. 19.05.2017

1st CORRIGENDUM AGAINST e-N.I.T. NO. – WBIW/SE/TBC/NIT-02(e)/2017-18 (2nd Call)

It is notified for general information that in respect of the Notice Inviting Tender No. WBIW/SE/TBC/NIT-02(e)/2017-18 (2nd Call), partial modifications have been made due to unavoidable circumstances as follows:

1. In Page No. 02 of 25: 'Source of Fund' under Column number 7 of e-NIT document:

In place of	To be read as
Core State Plan	State Government Fund

2. In Page No. 25 of 25: 'Copy with enclosure forwarded for information and taking necessary action please for wide publication to:', Sl. No. 2 of e-NIT document:

	In place of	ncia (To be read as
2.	The Chief Engineer, Teesta Barrage Circle, 2 nd Mile, Sevoke Road, Siliguri.	2. of I	The Chief Engineer, Teesta Barrage Project, 2 nd Mile, Sevoko Road, Siliguri.

All other details will remain unchanged.

(S. Chattopadhyay)
Superintending Engineer
Teesta Barrage Circle

Copy with enclosure forwarded for information and taking necessary action please for wide publication to:

- 1. The Chief Engineer, North East, Club Road, Jalpaiguri.
- 2. The Chief Engineer, Teesta Barrage Project, 2nd Mile, Sevoke Road, Siliguri.
- 3. The Superintending Engineer, Mahananda Barrage Circle, Teesta Administrative Building, Tinbatti, Siliguri.
- 4. The Principal Secretary, Department of Tourism, New Secretariat Building, 3rd floor, Block-A, 1-K.S. Roy Road, Kol.-700001.
- 5. The Superintending Engineer, North Bengal Mechanical & Electrical Circle, Tinbatti, Siliguri.
- 6. The Superintending Engineer, Teesta Resource Circle, Tinbatti, Siliguri.
- The Superintending Engineer, Teesta Design Circle, Tinbatti, Siliguri.
- The Superintending Engineer, Teesta Canal Circle, Karnojhora, Rajganj, West Dinajpur.
- The Superintending Engineer, North East Irrigation Circle-I, Club Road, Jalpaiguri.
- 10. The Superintending Engineer, North East Irrigation Circle-II, Club Road, Jalpaiguri.
- 11. The Executive Engineer, Teesta Monitoring & Evaluation Division, Teesta Administrative Building (Annex.), Tinbatti, Siliguri.
- 12. The Executive Engineer, Teesta Barrage Division, Oodlabari, Jalpaiguri.
- 13. The Executive Engineer, Teesta Irrigation Division, Assam More, Jalpaiguri.
- 14. The Executive Engineer, Teesta Left Bank Division, Oodlabari, Jalpaiguri.
- 15. The Executive Engineer, Mahananda Link Canal Division, Teesta Sech Bhavan, 2nd mile
- 16. The Executive Engineer, Teesta Quality Control Division, Tinbatti, Siliguri.
- 17. The Executive Engineer, DVC Study Cell, Irrigation & Waterways Department, Jalasampad Bhavan, 7th Floor, Salt Lake City, Kolkata-91,
- 18. Nodal officer of e-tendering, Irrigation & Waterways Department, Jalasampad Bhavan, 7th Floor, Salt Lake City, Kolkata-91, with the request to upload this NIT in the Departmental website:wbiwd.gov.in.

(Sent to the e-mail: dvcs6816@gmail.com/ irrigationhelpdesk@gmail.com)

- 19. The Head Estimator of Teesta Barrage Circle, 2nd Mile, Sevoke Road, Siliguri.
- 20. The Head Estimator, Teesta Barrage Project, 2nd Mile, Sevoke Road, Siliguri.
- 21. The Head Clerk of Teesta Barrage Circle, 2nd Mile, Sevoke Road, Siliguri.

THE QUELTY C

- 22. Office Notice Board.
- 23. Office File.

(S. Chattopadhyay) Superintending Engineer Teesta Barrage Circle

ME HARMENTA CO

the Head stain any of the state of the

Fallend Clerk of Jec 1-1 - one Chall